





Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name: Sally A. Gonzales		Daytime Phone: 303-371-8901
	Address: 3517	Delgany St.
Addresses of Properties covered by this Agreement:	Address:	
	Address:	
	Address:	
	Address:	

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed, the Grantor will have an opportunity to review and approve the planned soil removal, and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

Page 1 of 2





Consento para el Acesso de la Propiedad

DERECHO A ENTRAR LA PROPIEDAD

Otorgante (dueño(a) de propiedad) se da consento y autoriza la Agencia para la Proteccion del Medio Ambiente de Los Estado Unidos (EPA) o su representantes autorizado, en conjunto el Cesionario, a entrar y llevar a cabo algunas actividades ambientales acerca de la propiedad describido que sigue:

Dueño de la Propiedad: Sally A. Gonzales		Numero Diario:	
Dirección de Propiedades Cubieto por este Acuerdo:	Dirección: 3517 Del	lgany St.	
	Dirección:		
	Dirección:		_
	Dirección:		-
	Dirección:		

PROPÓSITO DE ACTIVIDADES AMBIENTALES

El EPA solicita el acesso a collectar muestras de tierra y remover tierra que tiene alta concentraciónes de arsénico y/o plomo que podría ser peligroso a su salud. La tierra estará removido y el(los) area(s) excavado(s) estará reemplazado con materials limpias y restaurado. Este trabaja estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de EPA se contactará el Otorgante pesonalmente a discutir el trabajo estar realizado, el Otorgante tendrá la oportunidad a examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termina, el Otorgante estará pedido a revisar el trabajo, confirmar su terminación y cumplir con su aprobación. Después de terminación, el Otorgante recibirá un documento escrito por el EPA que indica la propiedad había sido remediado.

ACCIONES DE LA RESPONDENCIA AMBIENTAL.

Por su firma de este Acuerdo de Acceso, el Otorgante concede el EPA, sus empleos, contractors y subcontractors el derecho a entrar la propiedad, en tiempos razonable y sin noticia anterior, para el unico propósito a realizar trabajo. Este acceso debería persistir en efecto hasta que el trabajo había sido terminado en un estado aceptado. El Ortogante tamiben está de acuerdo con:





- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact Jennifer Chergo.

EPA, at (303) 312-6601.

I grant access to my properties

I do not grant access to my properties

Signature

Date

Signature

Date

☐ I would like to be present during any sampling that is required.





- Remover obstruciónes que incluye botes, remolque, vehículos, jugetes de niños, montones de madera, casas de perros, etc.
- Remover de bulbos de flores, o otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener reemplazo de vegetación, incluso la aplicación de fertilizante, como es necesario subsecuente de la riega inicial por el EPA, a menos que regando está restringido por la Junta de Agua de Denver.
- Permanecer por la guia de Salud y Seguridad proveido por el EPA;
- Si la propiedad está rentado, asiste el EPA a obtener la aprobación del inquilino para acceso a la propiedad a llevar a cabo el trabajo, si el EPA está inhábil a obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad incluyendo los areas exterior y interior de edificios.

ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividades o trabajo hecho, o el equipo usado a llevar de cabo los actividades, o hacer cualquier acciones en respecto de la usa de dicho propiedad que podría arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor contacta Jennifer Chergo, EPA, (303) 312-6601.

		1	
☐ Si yo permito ac	ceso a mi propiedad	☐ No permito acce	so a mi propiedad.
		•	76.9
	·		
P			
Firma	Fecha	Firma	Fecha
			•
☐ Me gustaría ser	presento durante de cua	lquier colleción de mues	tras.
_		•	
		1	





Home About Denver Elected Officials Safety Neighborhoods Employment Doing Business Online Serv



Current conditient (9 ° Mostly Cloudy

Real Property Records

Date last updated: Friday, November 21, 2003

Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential

Name and Address Information

GONZALES, SALLY A

9380 KNOX CT

WESTMINSTER, CO 80031-2739

Property Address:

Parcel: 0227111010000

Legal Description

L 21 BLK 16 FIRST ADD TO

IRONTON RESIDENTIAL

Tax District

3517 DELGANY ST

DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	14100	1120		
Improvements	65400	5210		
Total	79500	6330	0	6330
Prior Year				
Land	9400	860		
Improvements	65000	5950		
Total	74400	6810	0	6810

Style: One Story

Year Built: 1890

Building Sqr. Foot: 737

Bedrooms: 2

Reception No.:

Recording Date: //

Document Type:

Sale Price:



Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions. now, or at any time in the future, except those items listed below, if any.

Property ID:
Property Address: 35 17 Delgany 57.
Owner: Sally A. Genzales
Phone: 303 371 - 8901
Restoration Items in Question:
Hem: Clothesline Dort -
Hem: Old Jence in back yard
tem: Diecos of broken conent left in alley
tem: Coursed up water meters with drive way
ttem: OSalel
item:
Additional Comments:
I agree restoration is completed, except as noted
I do not agree restoration is completed .
I agree that the sprinkler system is working properly following reinstallation by contractor
Saly Emplo 3-31-04 / 3/31/04
Owner's Signature Date Contractor's Signature Date



UNITED TATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
999 18th STREET, SUITE 300
DENVER, CO 80202-2466
Phone 800-227-8917
http://www.epa.gov/region08

Ref: 8EPR-SR

July 10, 2006

Larry L & Mary Jane Burgess 3 Red Fox Lane Littleton, CO 80127

RE: 3517 Delgany Street.

Dear Larry L & Mary Jane:

As part of the Vasquez Boulevard and Interstate 70 (VB/I-70) Superfund Site investigation, the United States Environmental Protection Agency (EPA) recently assessed your property at 3517 Delgany St. to determine if lead in peeling and chipping paint will re-contaminate the soils that EPA cleaned. *The results show your property qualifies for a lead-based paint abatement*. A lead-based paint abatement is a free, EPA action that will reduce or eliminate the areas of peeling or chipping paint on your house or other structures that will, in time, recontaminate the soil with lead.

EPA will be conducting lead-based paint abatements only through this summer. Specifically, the work will involve removing discrete areas of peeling and chipping lead-based paint, which EPA has determined will recontaminate the soil, and repainting those areas. The paint used will be matched to the current colors.

Please note that EPA will only remove and repaint lead-based paint on your property where it is currently peeling or chipping and where EPA has determined it will recontaminate your soil. This means that much of your property's external paint will continue to contain lead. As exposure to too much lead is a known health hazard, it is your responsibility as the property owner to maintain this paint in the future and prevent it from peeling. In this way, you can reduce the potential for lead-based paint exposure and/or soil recontamination from lead-based paint. Enclosed is documentation for suggested tips on how to maintain exterior paint.

Your property must be scheduled for a lead-based paint abatement this year. EPA will coordinate the activities with you to reduce any inconvenience to you. Representatives of EPA will be contacting you to discuss the lead-based paint abatement process. In the meantime, if you have further questions, please contact the VB/I-70 construction office at (303) 487-0377.

Sincerely,

Victor Ketellapper

Remedial Project Manager

United States Environmental Protection Agency (US EPA)





July 6, 2006

Dear Property Owner,

Project Resources Inc., a contractor for the EPA, is attempting to get in contact with you so that we may obtain access to perform a Lead-Based Paint Abatement at your property. We have an access letter that we need for you to sign so that we may perform the remediation. **Please contact us immediately** at the phone number listed below so that we may move forward with the abatement. It is very important that your property be remediated this summer as it is the final year of the project. Thank you very much and we look forward to hearing from you soon.

Our office phone number is 303-487-0377. Please leave your name, address, and phone number so that we may contact you.

Thank you,

Michael Vasquez

VB/I-70 Superfund Site Coordinator





Access Agreement

By signing this access agreement, the grantor is granting the EPA, US Army Corps of Engineers, its employees, contractors, and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the leadbased paint abatement work. This access shall remain in effect until the full remediation work is completed to include any and all work required to protect the soil remediation. This work will include but may not be limited to lead paint abatement sampling and documentation for the project.


303-956-8572

Phone Number

work is startal. Jan Buy



Facts About Lead



- Lead is a naturally occurring metal commonly found in the environment.
- Lead has no known nutritional value, but all people have some level of lead in their bodies
- Elevated levels of lead in the body can cause harmful health effects. Lead toxicity can affect the central nervous system including learning ability and development, blood systems, reproductive system and kidneys.
- Young children and fetuses are most sensitive to toxic effects of lead because their bodies are still developing.
- Lead poisoning can be prevented.

How are people exposed to lead?

Lead is found in many places in the environment. Some lead exists naturally in soils. Increased concentrations of lead are found in soils close to highways due to auto exhaust from leaded gas, in tailings from mining operations, emissions from metals refineries and waste incinerators, and from battery recycling operations. Lead may also be present in paint, water from lead-soldered plumbing, food from lead-soldered cans, some ceramic and pottery dishes, some folk remedy medications such as azarcon, greta, pay-loo-ah and kohl, and some hobbies such as making jewelry, bullets, fishing sinkers, stained glass and pottery with lead glazes.

Lead enters the body primarily through ingestion and inhalation. Children are more likely to put their hands and toys in their mouths, so are more likely to swallow lead from soil, dust and paint. Children and adults may be exposed to airborne lead from blowing dust or emissions from industrial activities such as smelting operations or waste incinerators.

What levels of exposure to lead have resulted in harmful health effects?

The type and severity of health problems associated with lead are dependent on several conditions:

- ► Amount of lead exposure;
- ► Length of the exposure;
- ▶ Age of the individual. Children may absorb up to 50% of the lead they ingest, while adults typically absorb only 10%. The nervous systems of children are also more sensitive to damage from lead.
- General health and nutrition of the exposed individual including iron, calcium or vitamin deficiency and use of alcohol and tobacco.


The average person in the U.S. today has less than 10 micrograms of lead per deciliter ($\mu g/dL$) of blood. In adults, levels over 25 $\mu g/dL$ of lead must be reported to the state health department, and can cause problems such as abdominal pain, anemia, damage to the kidney, and reporductive problems. Children and pregnant women are more sensitive to the effects of lead. At low levels of exposure (10-19 $\mu g/dL$), children often have no symptoms but may be at increased risk for behavioral problems and learning disabilities. Children born to mothers with blood lead levels exceeding 10 $\mu g/dL$ are at greater risk for lower birth weights, slower growth, decreased size and learning difficulties.

How can I prevent lead poisoning?

You can minimize exposure to lead by:

- washing your hands and your children's hands and toys frequently:
- wet mopping and dusting your home regularly;
- avoiding heating and storing food in open cans or ceramic pottery dishes;
- using caution when working with hobby supplies that contain lead;
- discouraging your child from playing in bare dirt and bringing dirt in from outside; and
- discouraging your child from putting non-food items (dirt, toys, paint chips) in their mouths.

You can also help decrease your body's absorption of lead by eating regular meals and a balanced, low-fat diet with plenty of iron, calcium and vitamin C.



#11

Web Ticket Entry

<> Inq New Update Test Cancel Reset Exit Ticket # 0000117741-000 has been queued!

Ticket 0000117741 Date 03/16/2004 Time 08:58AM Oper **JWL957208934**

Rev

Old Tkt 0000117741 Date 03/16/2004 Time 08:58AM

Oper **JWL957208934**

Cha

Phone 303-487-0377 Ext

Caller JASON LYNCH

Email JLYNCH@PROJECTRESOURCESING.COM

Company PROJECT RESOURCES

Fax 303-295-0990

Address 10 E 55TH AVE

City **DENVER**

State CO Zip 80216

Alternate Contact TODD MYERS

Phone 3034870377

Done for CORPS OF ENGINEERS / EPA

Work type SOIL EXCAVATION TO A DEPTH OF 12 INCHES F

Explosives N Boring **N** Meet time requested N

Place **DENVER**

St CO Cnty DENVER Addr From 3517

Street DELGANY STREET

Nearest Intersecting Street

Latitude Longitude

Location ENTIRE RESIDENTIAL PROPERTY FROM THE CURB AT THE ADDRESS LISTED ABOVE - SOIL EXCAVATION TO A DEPTH OF 12 INCHES FROM ENTIRE PROPERTY.

The locate will be completed between 03/16/04 09:14:40 AM and the end of the day 03

Grids (T/R/S) 03S068W27SW 03S068W28SE 03S068W33NE

Members ABOVENT1 ADSTA1 AHEC01 ATCT01 CDOT06 CMSDC00 CMSND13 CORK01 ICGTL3 LVL311 MCI01 MCLD01 PCDN01 PCDS01 PCND00 PSND13 QLNCND00 QLNCND13 QWST01 SGOXF1 SPRN01 TACO01 TWTEL1 WCG01 XOCOM1

Members - these will be notified by the center

AHEC01	AURARIA HIGHER EDUCATION CENTER	AURARIA HIGHER EDUC. CTR.
ICGTL3	ICG TELECOMMUNICATIONS AKA INTELCOM	ICG TELECOMMUNICATIONS
PCND00	XCEL ENERGY	XCEL ENERGY
PSND13	XCEL ENERGYAPPT FILE	XCEL ENGYAPPT SCHEDULE UQ
CMSDC00	COMCAST-CATV	COMCAST-CATV/UQ
QLNCND13	QWEST LOCAL NETWORKAPPT. SCHED.	QWEST LOCAL NETWORK
PCDN01	XCEL ENERGY	XCEL ENERGYDENVER NETWORK
PCDS01	XCEL ENERGY-DENVER STEAM	XCEL ENERGYDENVER STEAM
QLNCND13	QWEST LOCAL NETWORKAPPT. SCHED.	QWEST LOCAL NETWORK
XOCOM1	X O COMMUNICATIONS, INC	X O COMMUNICATIONS
LVL311	LEVEL 3 COMMUNICATIONS	LEVEL 3 COMMUNICATIONS
MCI01	MCI	MCI
MCLD01	MCLEODUSA (MCLEOD USA)	MCLEOD USA (FIBER)
WCG01	WILTEL COMMUNICATIONS LLC	WILTEL COMMUNICATION
QLNCND00	QWEST LOCAL NETWORK	QWEST LOCAL NETWORK (UQ)
ADSTA1	ADESTA COMMUNICATIONS	ADESTA COMM
QLNCND00	QWEST LOCAL NETWORK	QWEST LOCAL NETWORK (UQ)
ABOVENT1	ABOVE NET/MFN COMM	ABOVE NET/MFN COMM

PSND13 PCND00 SGOXF1 CMSDC00 CMSND13 CMSND13 QWST01 CORK01 CDOT06 TWTEL1 TAC001 ATCT01	ICG TELECOMMUNICATIONS AKA INTELCOM XCEL ENERGYAPPT FILE XCEL ENERGY SAGE-OXFORD INC. COMCAST-CATV COMCAST-APPT. SCHED. COMCAST-APPT. SCHED. QWEST COMMUNICATIONS COLORADO ROCKIES BASEBALL CLUB COLO DEPT OF TRANSPORTATION, REGION 6 TIME WARNER TELECOM TOUCH AMERICA - COLORADO AT&T	ICG TELECOMMUNICATIONS XCEL ENGYAPPT SCHEDULE UQ XCEL ENERGY SAGE-OXFORD, INC COMCAST-CATV/UQ COMCAST-CATV/UQ COMCAST-CATV/UQ QWEST COMMUNICATIONS COLORADO RKYS BSBL CLUB CDOTREGION 6 TIME WARNER TELECOM TOUCH AMERICA-COLORADO AT&T
ATCT01 SPRN01	AT&T U.S. SPRINT	AT&T U.S. SPRINT

TIER2 MEMBERS - you must notify these members yourself

DTEO01	DENVER TRAFFIC ENGINEERING OPERATIONS	DNVR TRAFFIC ENG OPERAT.	72
DNVH20	DENVER WATER DEPARTMENT	DENVER WATER DEPT	30
MWRD01	METRO WASTEWATER RECLAMATION DISTR	METRO WASTEWATER RECLAM	30
WWMG01	WASTEWATER MANAGEMENT DIVISION	WASTEWATER MGMT DIVISION	30
20SPM1	C/C DENVER, 20TH ST. PED. MALL MAINT.	20TH PEDESTRIAN MALL	30
DNVPR1	DENVER PARKS AND RECREATION	DENVER PARKS & REC.	30

Property Access Checklist

Property ID:		RK STARTED ON: / /	
Property Address: 3517 ORI		RK STARTED ON:/_/_ RK COMPELTED ON:/_/_	
3517 021	74/19 27		
Property Owner: Sally Gons	SAIES Property	Renter: Eddie	
Mailing Address:	Home P		
9380 Knox Ct. Westminister, Co	Fax:		
westminister, Co	Soc3 Cell/Pag	Cell/Pager: 720 297-9736	
Home Phone: 303 371-890	Addition	al Information:	
Fax:			
Cell/Pager: 720 297-97	36		
Eddie	· · · · · · · · · · · · · · · · · · ·		
Notification Letter	Sent: 12/15/0		
Access Agreement	Signed: 12/18/0		
Restoration Agreement	Signed: <u>1 / 13 / 0</u>	4 By: Sally Gonzales	
☐ Topsoil Sampling (if applicable)		Ву:	
Disposal Sampling (if applicable)	//	By:	
Garden Sampling (if applicable)		By:	
Utility Clearance	Called: / /	_ By:	
Video/Photos (Before)	On: 1/14/04	By: T. myers	
☐ Video/Photos (During)	On: / /	By:	
☐ Video/Photos (After)	On: / /	By:	
☐ Video/Photos (30-Day)	On://	Ву:	
☐ Property Completion Agreement	Signed: / /	_ By:	
☐ Final Report	Issued: / /	_ Ву:	
Air Monitoring (og applicable)			
Air Monitoring (as applicable) Community Crew On:	// By:		
Results:			
Community Crew On:	//_ By:		
Results:			
· · · · · · · · · · · · · · · · · · ·	// By:		
Results:			

Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: (
Property Address: 3517 12/5914 5+	
Owner: 59114 60075185	
Phone: 303 371-8901	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	
	Porch suing in front yard
Item:	
	Cars in front yard
Item:	
	weights in front yard and back
Item:	
	cement trim in front yard
Item:	
	trash bins in front yard
Item:	
	misc. Stuff glong side of Lanse
Item:	
	motorcycle in back yard by garage
Item:	/ // /
	motorcycle in back yard
	Tires in front 1910



Project Resources Inc.

Items To Be Removed By Contractor During Remediation And Not Replaced (Use additional sheets as necessary)

ltem:	
	NA
Item:	



🥕 Project Resources Inc.

Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)

Item:	NA			
Item:	7 / 11			
Item:		 7		
Item:	······································		· · · · · · · · · · · · · · · · · · ·	
Item:				:
Item:				
Item:				:
Item:				
Item:				
Item:				Ü

Landscape inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	1964	Square Feet	See Sketch
Number of trees > 2 inch trunk diameter	1		
Number of trees < 2 inch trunk diameter	~/A		NA
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	MA		Zones:A Heads:A Control Valves:A
Number of and total size of all gardens / flower beds.	# Of Beds:		Ft ² Of Beds: \mathcal{N}
Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft ² Of Gardens: W/A

Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft ² Of Beds To Be Replaced With Certificate:
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed: Include a sketch of were each plant will be placed by the contractor.	NA	Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	1177	SF	Total Ft ² Of Sod To Be Laid: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Ft ² :	SF	Sod: WA Driveway Grave 1 Brown Mulch: 701 Red Mulch: MA
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch:	SF	Red:/A

· Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock:	SF	Large: 85 Medium: NA Small (pea gravel): NA Driveway Gravel: 702
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover:		WIA

Additional Comments / Instructions:

renter has a large amount of items that must be moved prior to excavation.


Needs a few days notice.

Conly way to access back


Yard is through neighbors

yard at 3515 Delgany St.

	Additional Comments / I	nstructions Continued:	
		•	
	•		
·			
pre-existing damag	if Owner does not want PRI to ge. By checking this box PRI in acluding foundation cracks or fiss	s not responsible for an	
☐ I agree	I do not agree	☑ I agree	☐ I do not agree
	n	\sim 1	
Dallylo	m pales 1-13-04	Combra	1/13/04
Owner's Signature	Date Page	Contractor's Signatur	re Date




(2)



1) 11-01- DWC	1400 HOURS	08-26-06	
2) /1- poz- Dwc	1410 HOURS	a3-26-06	
3)/1- 001- SCC	1420Hairs	■ 08-26-06	•
4)/1-002-506	1430 Hours	· 08-26-06	
5)	·		•
6)			

This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 3517 Delgany St.

INPUTS	Variable	Units	House
General	Mixing depth in yard	cm	2.54
	Mixing depth in yard	inches	1
	Soil density	g/cm3	2.5
	RBC in soil	mg/kg	400
	Bkg in clean fill	mg/kg	50
			Small
House-specific	Area of the exposure unit	m2	99.22045
	Area of the exposure unit	ft2	1068
	Concentration of lead in paint	mg/cm2	27.7
	Area of peeling paint		20.90318
	Area of peeiing pairs	ft2	225
COMPUTATIONS			
	Mass of lead from paint	mg	5.8E+06
	Volume of soil	cm3	2.5E+06
	Mass of soil	kg	6.3E+03
	Incremental concentration	mg/kg	919.0
	Maximum acceptable area of p	- -	8.0
	Maximum acceptable area of p		85.7
DECISION			Not OK



North South East West

Exterior Walls				Doors (Trip)					
Material	Area	Peel/Chip XRF (Lead)		Area Peel/Chip XRF (Lead) Material		Material	Area	Peel/Chip	XRF (Lead)
NOOD	_	_	,	WOOD					
51/NG16			-	4000			-		
DOOM	~~		1.9	WooD		CRACK	4.6		

Total

Total

North South East West

Window Trim/Fascia/36ffit				Patios/Decks/Porches				
Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)	
WOOD	41'0	PELL	2,3	WOOD	182'4	PEEL	13.7	
WOOD	2'4	parl	27.7					
WOOD	<i>-</i>		_	Wado		CRACK	12.9	
					·			
Total				Total				

North South East West

Metal Trim/Gutters/Downspouts				Misc Structures/Garage/Fences				
Material	Area		XRF (Lead)		Area	Peel/Chip	XRF (Lead)	
in the state of th		را المان المان الموافقة	The state of the s	Style Services	:- •			
				WOOD			-	

Total

Total

Time	Site	Component	Substrate	Side	Condition	Color	Floor	Room	Results	Depth Inde	PbC	PbC Error
8/13/2005 9:20	11	COLUMN	WOOD	EAST	CRACKED	WHITE	FIRST	PORCH	Positive	7.56	12.9	1.6
8/13/2005 9:21	11	WINDOW FRAME	WOOD	EAST	CRACKED	WHITE	FIRST	PORCH	Negative	1	0	0.02
8/13/2005 9:22	11	SIDING	WOOD	EAST	CRACKED	GREEN	FIRST	PORCH	Positive	10	1.9	0.4
8/13/2005 9:25	11	SIDING	WOOD	SOUTH	CRACKED	GREEN	FIRST	OUTSIDE	Negative	4.21	0.04	0.04
8/13/2005 9:26	11	DOOR FRAME	WOOD	NORTH	PEELING	BROWN	FIRST	OUTSIDE	Negative	1.92	0.01	0.02
8/13/2005 9:27	11	WINDOW FRAME	WOOD	NORTH	PEELING	WHITE	FIRST	OUTSIDE	Positive	3.35	27.7	2.
8/13/2005 9:28	11	SIDING	WOOD	NORTH	INTACT	WHITE	FIRST	OUTSIDE	Negative	1.84	0.01	0.02
8/13/2005 9:29	11	DOOR	WOOD	WEST	CRACKED	WHITE	FIRST	OUTSIDE	Negative	3.4	0.6	0.1
8/13/2005 9:30	11	WINDOW FRAME	WOOD	WEST	CRACKED	WHITE	FIRST	OUTSIDE	Negative	2	0.06	0.04
8/13/2005 9:32	11	SIDING	WOOD	EAST	INTACT	GREY	FIRST	SHED	Negative	1.66	0.01	0.0
8/13/2005 9:38	11	SIDING	WOOD	EAST	INTACT	GREEN	FIRST	PORCH	Negative	5.87	0.13	0.1
8/13/2005 9:39	11	SOFFIT	WOOD	EAST	CRACKED	WHITE	FIRST	PORCH	Positive	3.78	4.6	0.6
8/13/2005 9:41	11	SOFFIT	WOOD	NORTH	PEELING	WHITE	FIRST	PORCH	Positive	2.99	2.3	0.3
8/13/2005 9:42	11	SIDING	WOOD	NORTH	PEELING	WHITE	FIRST	PORCH	Negative	2.25	0.08	0.04
8/13/2005 9:43	11	COLUMN	WOOD	NORTH	PEELING	WHITE	FIRST	PORCH	Positive	10	13.7	1.6
Notes Deadings	in m											
Note: Readings a	tre in M	g/cm-					 	 				
Painted surfaces	not tes	ted were assessed	to be in "i	ntact" con	dition at time	of site vis	it.	<u> </u>				

Color Photo(s)


The following pages contain color that does not appear in the scanned images.

To view the actual images, contact the Region VIII Records Center at (303) 312-6473.

Property ID # 11 / 3517 Delgany Street



East porch exposure of house



Porch ceiling / soffit contains peeping lead paint

TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1034347

DOCUMENT NUMBER: 1004047	
SITE NAME: VASQUEZ BOULEVARD AND I-70	
DOCUMENT DATE: 12/18/2003	٠
DOCUMENT NOT SCANNED Due to one of the following reasons:	
☐ PHOTOGRAPHS	
☐ 3-DIMENSIONAL	
□ OVERSIZED	
☑ AUDIO/VISUAL	
☐ PERMANENTLY BOUND DOCUMENTS	·
□ POOR LEGIBILITY	
□ OTHER	
□ NOT AVAILABLE	
☐ TYPES OF DOCUMENTS NOT TO BE SCANNED (Data Packages, Data Validation, Sampling Data, CBI, Chain of Cust	ody)
DOCUMENT DESCRIPTION:	
DVD OF PROPERTY VIDEO, PROPERTY #11 CD OF PROPERTY DATA	